


Technical Service Information

Title **FRONT STABILIZER BUSHING NOISE**

Page 1 of 1

A new teflon lined front stabilizer bushing is now available to eliminate front stabilizer bushing noise. This new bushing was introduced on the 1995 LS 400, and will also fit '90-'94 model year LS 400's.



MODEL APPLICATION:

1990 – 1994 LS 400

PART NUMBER INFORMATION:

PREVIOUS PART NUMBERS	NEW PART NUMBER	DESCRIPTION	QTY.
48815-50011 48815-50120	48815-50121 "	Stabilizer Bushing "	2

Both front bushings must be replaced as a set.

WARRANTY INFORMATION:

OPCODE	DESCRIPTION	TIME	OPN	T1	T2
430211A	Front Stabilizer Bushing (Both sides, R & R)	0.6	48815-50011 48815-50120	91	55